

## Addendum to V1190-1290 User's Manual



The printed boards of the V1190 an V1290 Modules with V1X90 Customization - Hardware Enable for 2ESST (Ordering Code <u>WPERS001X90E</u>), in order to pilot the RETRY signal on the VME Bus (necessary for larger block transfers with 2eVME and 2eSST modes when running Firmware Rev. 0.9), were modified and therefore they have the IRQ Line 4 disabled.